

## WESTBAY® RETROFIT WELL SUMMARY

Page 1 of 6

**Location ID:** JP-3

**Field Representatives:** Canavan, Giles,  
Hunnicut-Mack, McClure, Pearson, Rivera

**Purpose of Well:** To monitor plume-front contamination and the effectiveness of the  
water treatment system for plume stabilization.

**Date Started:** 1/23/99

**Date Completed:** 9/2/99

**Northing:** 227464.71

**Easting:** 396409.23

**Brass Cap:** 4433.54'

**Outer Casing:** 4434.43'

**Inner Casing:** 4434.47'

**Drilling Method:** Mud Rotary

**Drilling Contractor:** Stewart Brothers Drilling Company

**Driller:** Paul Hollar

**Total Depth Borehole:** 1020'

**Diameter Borehole:** 12.25" to 105';  
Reamed to 17.5"; 12.25" to TD.

**Total Depth Surface Casing:** 103'

**Diameter Surface Casing:** 14" OD

**Total Depth Conv. Well Casing:** 1005'

**Diameter Conv. Well Casing:** 4.5" OD

**Total Depth 1.5" OD Westbay® Casing:** 995'

**Water First Detected:** Not detected  
during drilling

**Water Level Open Borehole:** 433'  
(from geophysical log)

**Water Level Conv. Cased**  
**Borehole (post-development SS):** 369.24'

**Estimated Water Use (pre- development):**  
89,600 gallons

### Sampling Zones

<u>Screened Zone</u>	<u>Sand Pack</u>	<u>Westbay® Zone</u> <u>(packer to packer)</u>	<u>Meas.</u> <u>Port Depth</u>
<u>508.53' to 518.57'</u>	<u>499' to 524'</u>	<u>505' to 525'</u>	<u>515'</u>
<u>688.89' to 698.98'</u>	<u>684' to 705'</u>	<u>685' to 705'</u>	<u>695'</u>
<u>819.17' to 829.26'</u>	<u>814' to 835'</u>	<u>815' to 835'</u>	<u>825'</u>
<u>964.52' to 974.61'</u> <u>(continued next page)</u>	<u>960' to 982'</u>	<u>960' to 980'</u>	<u>970'</u>

**Conventional Well Casing Used**Diameter: 4.5" ODStainless Steel Type: 304**Schedule 5****Schedule 10**5-foot: 0 = 0 ft5-foot: 1 = 5 ft10-foot: 0 = 0 ft10-foot: 4 = 40 ft20-foot: 0 = 0 ft20-foot: 46 = 920 ftTotal Sch 5 Footage = 0 ftTotal Sch 10 Footage = 965 ftTotal Footage of Blank Risers: 965 ftStick-Up: 2.6 ft originally. Cut to 1.6 ft  
8/99. Final stick-up (from  
brass cap) = 0.89 ft**Screen Used**Diameter: 4.5" ODSlot Size: 0.020"Stainless Steel Type: 304**400-600-ft Depth Rating****600-1000-ft Depth Rating**5-foot: 0 = 0 ft5-foot: 0 = 0 ft10-foot: 1 = 10 ft10-foot: 3 = 30 ft20-foot: 0 = 0 ft20-foot: 0 = 0 ftTotal Footage of Screen: 40 ft**Annular Materials**

Based on field notes and drill reports (approximate totals only).

Sand, grade 10/20100-lb. Bags: 050-lb Bags Benseal: 13350-lb. Bags : 60100-lb. Buckets: 52094-lb. Bags Cement: 115Sand, grade 30/7050-lb. Bags: 19Sand, grade 16/4050-lb. Bags: 26100-lb. Buckets: 0

(continued next page)

**Westbay® Casing Used:**10-foot: 87 = 870 ft5-foot: 15 = 75 ft2-foot: 1 = 2 ftPacker: 10 = 50 ft      Total Footage: 997 ftRegular Couplings: 98      Well Depth: 995 ftPumping Ports: 4      Stick-Up: 2 ft joint; 1.71 ft (0.11 ft above  
stainless steel 8/99) Final stick-up  
(from brass cap) = 0.93 ftMeasurement Ports: 10End Caps: 1Magnetic Collars: 4**Pertinent Field Notes**

For more detail, refer to Field Notebook #s DP 392/RFI/CMS (pages 22-27; 50-73; 76-80; 82-86; 88-92); TDP 392/RFI/CMS (pages 16-18; 31-35); Development #1 (pages 39-42; 63-64; 66; 68); Westbay® Installation (pages 49-59).

- 1/23/99- Mobilized to site, rigged up and mixed mud. Spud borehole. Drilled mud rotary 12.25" pilot borehole to 65'-L. Hunnicutt.
- 1/24/99- Drilled pilot 12.25" borehole from 65'-105'. Reamed borehole to 17.5" from 0'-105' below ground surface-L. Hunnicutt.
- 1/25/99- Installed 14" outside diameter (OD) surface casing to 103' and grouted to surface-L. Hunnicutt.
- 1/26/99- Rigged down, decontaminated rig and pipe, and mobilized to ST-7-M. McClure.
- NOTE- Drilled pilot borehole and set surface casing at ST-7. Then, installed stainless steel casing at WW-2 before returning to JP-3 to complete drilling.
- 2/16/99- Remobilized to JP-3 (from WW-2). Drilled mud rotary 12.25" borehole from 103'-170'-L. Hunnicutt.
- 2/17/99- Drilled 170'-480'. Borehole deviation was ¼° from hole origin-M. McClure.

(continued next page)

**Pertinent Field Notes Cont.**

2/18/99- Drilled 480'-685'. Borehole deviation was 0.8° from hole origin-G. Giles.

2/19/99- Drilled 685'-765'. Reconfigured stabilizers to maintain borehole deviation < 1°. Borehole deviation was 1° from hole origin-G. Giles.

2/20/99- Drilled 765'-967'. Borehole deviation was ½° from hole origin-L. Hunnicutt.

2/21/99- Drilled 967'-1020' (Total Depth). Borehole deviation was just over ½° from hole origin. Tripped out. Geophysical logging began by Southwest Geophysical Services, Inc. (Electric log and Neutron logs completed)-L. Hunnicutt.

2/22/99- Geophysical logging was completed (caliper, sonic, drift logs). Tripped in 2" tremie pipe-L. Hunnicutt.

2/23/99- Installed 4.5" OD stainless steel casing to 1005' with 2.64' stick up. Installed annular materials to 982' (up to the sand pack of the bottom screen)-L. Hunnicutt and M. McClure.

2/24/99- Installed annular materials from 982'-835' (up to the sand pack of screen #3)-M. McClure.

2/25/99- Installed annular materials from 835'-736' (between screen #3 and screen #2)-M. McClure.

3/2/99- Installed annular materials from 736'-617' (between screen #2 and screen #1). Varying yields for materials. Bridging?-L. Hunnicutt.

3/3/99- Installed annular materials from 605' (after surging)-394'-M. McClure.

3/4/99- Installed annular materials from 394'-190' and grouted to 170'-G. Giles.

3/5/99- Grouted from 170-surface. Decontaminated rig and pipe and moved to ST-7-G. Giles.

NOTE- For many dates, development summaries are taken from the development sheets, and no other details are available.

3/6/99-

3/7/99- Bailed well. 1,278 gallons removed. Water changed from medium brown and soapy to tan-brown and still soapy- G. Giles, L. Hunnicutt, J. Pearson, and M. Rivera.

3/24/99-

4/11/99- Swabbed well. 310 gallons removed from first screen (top). Water was black and slimy; 1,050 gallons removed from screen #2. Water dark gray; 800 gallons from screen #3. Water was greenish, yellowish gray and cleared significantly; 1,050 gallons removed from screen #4. Water initially brown but clearing-M. McClure, J. Pearson, and M. Rivera.

(continued next page)

**Pertinent Field Notes Cont.**

4/12/99-  
4/14/99- Pumped well. 3,280 gallons removed from the bottom screen; 420 gallons from screen #3; ~2,000 gallons from screen #2; and ~2,000 gallons from the top screen-G. Giles and J. Pearson.

NOTE- Completed development (bailed, swabbed, and pumped) at BLM-38, BLM-39, and (pumped) at BLM-36; completed development (bailed, swabbed, jetted, and pumped) at ST-7 and PL-8; bailed and swabbed BLM-37; and installed Westbay® casing at BLM-36, BLM-39, and ST-7 before continuing JP-3 development.

7/11/99-  
7/12/99- Jetted well. Unchlorinated Well J water was used to jet each screen twice (6,400 gallons; a total of 25,600 gallons was jetted into the well)-L. Hunnicutt-Mack and J. Pearson.

NOTE- Pumped BLM-37 and 700-J; airlifted, jetted, and pumped IS-2; and installed Westbay® casing at 700-H before continuing JP-3 development.

8/12/99-  
8/18/99- Pumped well. 8,144 gallons from screen #1. Turbidity was 1.22 NTU; 6,169 gallons from screen #2; 8,279 gallons from screen #3. Turbidity was 1.21 NTU; 8,273 gallons from screen #4. Turbidity cleared from 2.51 to 1.35 NTU-M. Canavan and J. Pearson.  
Development complete. Waiting for camera log to install Westbay® casing.

8/24/99- Camera logged the well. The water above the first screen was cloudy, but clear within all four screens.

8/24/99- Pumped 500 gallons total from well at 30 foot intervals while tripping up one joint at a time to clear water above the screens-M. Canavan.

8/25/99- Set up tables and Westbay® MP 38 1.5" OD PVC casing, and performed two QA/QC checks. Tested tool (injection valve pressure). New pressure control unit (PCU) (box number two) leaked water from the pressure valve setting. Continued with PCU number one. Installed 225' of casing (995'-770')-M. Canavan and L. Hunnicutt-Mack.

8/26/99- Completed Westbay® MP 38 casing installation (from 770'-surface). Set up for packer inflation. Began casing integrity (leak) test with 186' head differential-M. Canavan and L. Hunnicutt-Mack.

8/27/99- Leak test completed. Casing did not leak. Inflated packers one and three and partially inflated the fourth packer (2.0 liters). Broke down equipment for weekend-G. Giles, L. Hunnicutt-Mack, and J. Pearson.

(continued next page)

**Pertinent Field Notes Cont.**

- 8/30/99- Set up equipment to complete packer inflation. Retested tool pressure and performed blank wall test. Completed inflating packer four and inflated packer number two. PCU number one was replaced with a new PCU sent from Westbay® (PCU number three) because of fluctuations in the pump pressure-G. Giles.
- 8/31/99- Inflated packers five and six and partially inflated packer seven (1 5/8 liters). Reservoir return hose was leaking. Re-cut and clamped hose-L. Hunnicutt-Mack.
- 9/1/99- Completed inflating packer seven. Inflated packers eight and nine partially inflated packer ten (1.5 liters)-L. Hunnicutt-Mack.
- 9/2/99- Completed packer inflation (packer ten). Cleaned up site-G. Giles. Installation complete. Turned well over to Technicians for Westbay® development.